

HISTORY

- Houses at Start: 35
- Occupied Houses Deemed Uninhabitable: 3
 - Population at Start: 112
 - Percentage of Land Undeveloped: 44%
 - **■** Work Completed: Housing, Water, Sewer, Streets, Drainage
 - Improvement Costs: \$1.7 Million
 - Revitalization Completion: 1986

MILL DAM

Background

LOCATION: Located in the Great Neck study area, Mill Dam is bordered on the north by Great Neck Manor subdivision, west by a line midway between Great Neck Road and Shoveller Avenue, south by Sandee Lake subdivision and east by Mill Dam Creek.

POPULATION: 125 persons

COMPOSITION: 89% minority

ZONING: Mill Dam is zoned R-5, medium density.

REZONING: During the past five years, only four rezoning applications have been submitted. All were to rezone to A-1.

LAND USE: Mill Dam is 56% developed (by parcel), single family residential. 44% is undeveloped.

ADJACENT USE & ZONING: Mill Dam Community is predominately surrounded by residential development (R-5, R-8) including a new town house subdivision, Great Neck Town Houses (A-1). Southwest of the community the area is zoned B-2 where a new veterinary clinic, children's nursery and 7-ll convenience store have been built.

UTILITIES: Mill Dam is presently undergoing the installation of water and sewer lines. Street improvements are also in progress.

HOUSING: 51% of the existing housing in Mill Dam is considered feasible for rehabilitation according to the guidelines established in the City of Virginia Beach property rehabilitation standards. 31% is infeasible, 3% new and 11% vacant infeasible.

EDUCATION: The Mill Dam Community is located within the school zones of John B. Dey Elementary, Great Neck Junior High and Cox High School.

TRANSPORTATION: T.R.T. serves First Colonial and Great Neck Roads.

SPECULATION: Land Use: Vacant 41% Absentee Residential 26% Absentee

Zoning: 100% of parcels zoned R-5 32% Absentee

Note: Absentee ownership excludes city, state and federal.

MILL DAM

Community Development Land Use Issues

- As waterfront property, Mill Dam must concern itself with water quality and natural habitat being disturbed by development, grading, run-off and erosion.
- 2. Mill Dam community has experienced traffic increases along First Colonial Road as well as Great Neck Road.
- Mill Dam has also been subject to increasing noise levels due to the increasing amount of daily traffic and due to the adjacent commercial uses on Great Neck Road.
- 4. The community of Mill Dam is divided by a man-made barrier, Mill Dam Road (Old First Colonial Road) as it cuts through the middle of the target area. With this division of such a linear nature, it will be difficult for both sides of the Mill Dam community to maintain cohesiveness.
- 5. At one time, a proposal to abandon Mill Dam from the community development program was submitted, but the community league expressed opposition and pressured the council into maintaining it as a target area. The community remains divided on this issue.

MILL DAM

Community Development Land Use

Recommendations

OVERALL

- A. Mill Dam should remain a single family residential community of low density.
- B. Mill Dam is not of sufficient size or density to remain a viable Community Development neighborhood.

SPECIFIC

- 1. The project boundary lines should be redrawn to exclude vacant property (see map).
- 2. Any development or redevelopment should require that a planting buffer and fence be established between land zoned B-2 and any residential zoning district (see map).
- 3. No development should be allowed which would displace existing wetlands (see map).
- 4. Any fill and fill areas should be strictly controlled as to both the placement of fill material and the type of fill material.
- 5. All existing roads should be improved to a 50-foot right of way.
- 6. A separate, detailed study of this area should be undertaken, with its purpose being to establish a program to disengage the Department of Housing and Community Development from this neighborhood.